



Project: Cooler Tower Basin Repair



The Problem

The client was having problems with this cooling tower basin at a nuclear power plant because it was in desperate need of repair. The basin was deteriorating, the concrete wall was badly cracked and wearing away and corrosion was affecting the exposed metal.

Unconventional Solutions was called in to solve the problem.

The Solution

The exposed rebar was coated with **USI Ultimate Protection Coating**, a high build epoxy designed to provide excellent, long-term corrosion protection in one coat.

The damaged concrete was prepared and repaired with **USI Concrete Mortar LW**. This lightweight repair mortar is excellent for vertical or overhead surfaces. It provides a strong, durable repair to any concrete or mineral, and is 100% solid and VOC free. This lightweight mortar gives the customer 6000 psi of compression strength.

