

Project: Concrete Stairs Repair



The Problem

The project requirement was to completely repair and coat the stairway in this recreation area, which serves as a main access route.

A heavy-duty repair system was sought due to the "high wear" environment.

The Solution

Cleaning and abrading of the surface of the repair area was completed before the application of a tack coat of **USI Concrete Repair Primer**. The damaged areas were then rebuilt using **USI Concrete Repair LW** which is a three component, solvent free, heavy duty epoxy repair mortar.

The entire surface of the concrete stairway was then coated with 3M Scotchkote Urethane Primer FB 856.

The stairs were no longer a safety hazard and the company was extremely satisfied with the quick and easy results.

