

Compressor Station Maintenance



PROBLEM

Coal tar epoxy was starting to fail at a compressor station. They were interested in a high performance, long-term solution.

SUBSTRATE

Metal

PRODUCTS USED

[3M Scotchkote 323+](#)

SOLUTION

[3M Scotchkote 323+](#) was selected, and the contractor liked that Unconventional Solutions stocked the product. Additionally, the USI team had the product there the same day due to the “hot shot” delivery service.