

## Power Plant Coal Mill Ceramic Tiles



### PROBLEM

This great lakes power plant had a severe problem with ceramic tiles chipping and popping out. As you can see from the picture there was extensive damage to the ceramic Tile. Unconventional Solutions had been making regular monthly visits to this Power Plant, our technical sales consultant had become a trusted advisor and recommended Resimetal 204 HD, during a lunch and learn.

### SUBSTRATE

Tile

### PRODUCTS USED

[Resimac 204 UHD](#)

### SOLUTION

USI presented a lunch and learn that provided insight and education on how to extend the life of chutes and power hoppers to the maintenance team.

When the power plant maintenance team identified the need, they already had [Resimac 204 UHD](#) on the shelves. They were able to use it to make a long-term repair.