

Containment Area Repair



PROBLEM

The EPA was about to fine this automotive engine manufacturer for the condition of their secondary containment. This containment area was in need of repairs and a new chemical resistant lining.

SUBSTRATE

Concrete

PRODUCTS USED

[Resichem 576 Quartz Screed](#)
[Resichem 571 Concrete Repair LW](#)
[Resichem 503 SPEP](#)
[Resichem 501](#)
[USI Fast Striping Line Marker](#)

SOLUTION

As you can see, we repaired many cracks but also added burms to make the flow go in the proper direction. The product used here was [Resichem 576 Quartz Screed](#).

After repairing the concrete and adding the burms, [Resichem 571 Concrete Repair LW](#) Unconventional Solutions sealed the area with and [Resichem 503 SPEP](#) followed by [Resichem 501](#).

USI then coated the yellow striping with [USI Fast Striping Line Marker](#).