

## Church Steeple Roof Line Repair



### PROBLEM

This church was having issues with moisture in the steeple at the roof line.

This moisture was penetrating the roof and going into the ceiling, causing issues with the lights.

The church was looking for an effective and long-lasting repair solution that would prevent the moisture from doing any further damage.

They wanted a solution that would be easy and save them time while applying it.

### SUBSTRATE

Asphalt shingles and Aluminum

### PRODUCTS USED

[Viscotag Sealant](#)

[Viscotag EZ Wrap](#)

### SOLUTION

[Viscotag Sealant](#) was used to repair the steeple roof line and prevent moisture from causing further damage.

The viscoelastic sealant was used to seal the area where the base of the steeple meets the roof. Then, the sealant was covered with [Viscotag EZ Wrap](#) for added protection.

The church was very happy with the outcome of the project, and with how easy it was to use and apply our products.

The repair lasted for 12 years until an overly ambitious roofing contractor removed it.