

Containment Area Repair



PROBLEM

The EPA was about to fine this truck diesel repair for the condition of their secondary containment. Unconventional Solutions was called in to save the day!

SUBSTRATE

Concrete

PRODUCTS USED

[RESICHEM 576 Quartz Screed](#)
[RESICHEM 571 Concrete Repair LW](#)
[RESICHEM 503 SPEP](#)
[RESICHEM 511 UCEN](#)

SOLUTION

USI repaired the concrete lining, which includes the floors and walls.

[RESICHEM 576 Quartz Screed](#) was used to rebuild the floor and [RESICHEM 571 Concrete Repair LW](#) was used to rebuild the vertical surfaces on the walls.

After repairing the concrete, we primed the area with [RESICHEM 503 SPEP](#) and sealed it with [RESICHEM 511 UCEN](#) for chemical resistance.