

Lookout Station Corrosion Protection



PROBLEM

The Army Corps of Engineers Look Out Station was grappling with the detrimental impact of corrosion, which was progressively weakening its structural integrity and compromising its overall functionality.

SUBSTRATE

Steel

SOLUTION

They didn't want to abrasive blast so close to Lake Erie so after talking to Unconventional Technical Sales Consultant they liked the idea of getting Technical Support, Training and Troubleshooting.

They ultimately chose Resimac Resinox 555 in 2011 for the project.

PRODUCTS USED

[Resimac Resinox 555](#)