



Unconventional Solutions, Inc.

YOUR REPAIR AND PROTECTION ALTERNATIVE

www.unconventionalsolutions.biz

Project: Tank Chime Repair



The Problem

A waste water company was looking for a cost-effective and durable repair solution for their tank chimes. There was a 1½in. gap that needed to be repaired and sealed.

The company also wanted to save time with a solution that is easy to apply.

The Solution

- *Adheres to almost any surface*
- *No primer or cure time required*
- *Permanent solution for water leaks*

Unconventional Solutions used a viscous elastic sealant, a mastic-like paste with synthetic properties to seal the gap at the base of the tank chime.

To protect from further corrosion, the sealant was then covered with a 70 mil viscous elastic wrap that can be painted immediately.

Since the floor plate of a tank is constantly moving during the filling and emptying process, the permanent flexibility and aggressive adhesion of this viscous elastic system is ideal for tank chime areas.



Unconventional Solutions, Inc.

28056 Oakland Oaks Ct.

Wixom, MI 48393

248-735-7000

www.unconventionalsolutions.biz