



## Project: Stainless Steel Conveyor Dearborn, Michigan



### The Problem

This stainless steel Flat Top Conveyor in a local Auto Plant was constantly getting wet causing a major slip hazard to the assembly drivers.

Unconventional Solutions was called in to solve the problem.

### The Solution

The conveyor was cleaned and coated with our **3M Scotchkote Epoxy Coating 152 LV** with **3M Scotchkote LD Grip 092** system to offer the assembly plant a long term solution over the conventional safety tape.

