



Experts in Composite Repair and Protective Coatings

MI 248.735.7000 | OH 937.704.4220

www.USIgroups.com

## Project: Stairway Repair



### The Problem

This building is protected by the state as a unique architectural construction.

The requirement was to repair the staircase which had deteriorated badly and return it to its original appearance.

### The Solution

The damaged areas were rebuilt with **USI Concrete Repair LW**, a high performance concrete repair product, due to the heavy usage that occurred on the staircase.

The staircase was then recoated with decorative coating systems to return it to its original condition.

