



MI 248.735.7000 | OH 937.704.4220  
www.USIgroups.com

## Project: WWTP Clarifier Tank



### The Problem

The weather had been taking its toll on the clarifier tank at this waste water treatment plant, causing the concrete to erode and begin to crumble.

The management at this plant needed the eroding concrete to be repaired with a product that would also provide protection against the elements.

### The Solution

The concrete surface was scarified to remove any existing coating that remained and to obtain a smooth profile. The crew used **USI Epoxy Sealer** to seal the surface and then applied **USI Quartz Screed** to rebuild the wall.

**USI Quartz Screed** is a high-performance, re-surfacing screed designed for use on concrete that is subject to abrasion and chemical attack.

**USI Quartz Screed** is recommended for concrete and floors even in the most aggressive environments.

