

## Power Plant Coal Mill Ceramic Tiles



### PROBLEM

This Great Lakes power plant had a severe problem with ceramic tiles chipping and popping out. As you can see from the picture there was extensive damage so Unconventional Solutions was called in to help with this repair.

We were their first call because of our expertise and our chosen solutions which could provide a long-term solution.

### SUBSTRATE

Tile

### PRODUCTS USED

[Resimac 204 HD](#)

### SOLUTION

USI presented a lunch and learn that provided insight and education on how to extend the life of chutes and power hoppers to the maintenance team.

When the power plant maintenance team identified the need, they already had [Resimac 204 HD](#) on the shelves. They were able to use it to make a long-term repair.