



## Project: St. Clair Floor Repair



### The Problem

Major Great Lakes Power Plant was experiencing “trips & fall” hazards in their warehouse. Employees were going in and out and the concrete was over 50 plus years old. It had started to crumble in many spots, and they did not have time to cut out and pour new.

### The Solution

USI was called in to look at the problem and come up with reliable solutions. The customer liked the fact it could be done over a long-weekend (Friday-Sunday).

The solution consisted of **USI Epoxy Sealer SP** and **USI Concrete Repair** to rebuild the damaged concrete areas.

**USI Epoxy Floor Coating HB** was used to give it a safe and easy to clean surface with some added LD Grip to help eliminate the #1 OSHA reportable “Trips & Falls”. As you can see the results turned out fabulous.

