

Compressor Station Valve



PROBLEM

Some valves at compressor station needed a new coating, as an alternative to coal tar.

SUBSTRATE

Metal

PRODUCTS USED

[3M Scotchkote 323+ Spray System](#)

SOLUTION

The coal tar was grit blasted off to achieve a NACE #2 near white metal finish and a two-to-four-millimeter anchor pattern.

Next, [3M Scotchkote 323+ Spray System](#) was applied to save time and money. This resulted in fewer jeeps than the brush grade, which allows them to back fill quicker.