

Break Room Floor



PROBLEM

The break room floor at this steel company was damaged from everyday wear and tear. The concrete floor in this 800 sq. ft room was beginning to crack, creating a hazardous environment for the employees and the company.

Unconventional Solutions was called to find an alternative to replacing the entire floor.

SUBSTRATE

Concrete

PRODUCTS USED

[USI Flexible Primer](#)

[USI High Build](#)

SOLUTION

The break room floor surface was cleaned. Then the surface was prepped with a diamond wheel grinder to give the floor the proper surface profile.

After surface prep was completed, [USI Flexible Primer](#). [USI Flexible Primer](#) is a solvent free floor primer that offers excellent adhesion to concrete surfaces. The floor was then coated with [USI High Build](#), a high build, ceramic enhanced, solvent free floor coating. [USI High Build](#) provides a high-performance finish with good abrasion and chemical