

Crumbling Concrete Wall



PROBLEM

This concrete wall was cracking due to the fact of the Great Lakes freeze though cycle. It had been replaced several times before.

SUBSTRATE

Concrete

PRODUCTS USED

RESICHEM 571 Concrete Repair LW

SOLUTION

Unconventional Solutions assisted in the repair using RESICHEM 571 Concrete Repair LW.